


State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

| Date of Notification (1) 07/01/2016 | | Name of Building Owner/Operator (2) US Army Installation Management Command | | | | | | | |
|--|--|---|---|--|---------------------------|----------------|--------|--------------------|-----------|
| Agencies Notified <input checked="" type="checkbox"/> EPA <input type="checkbox"/> DEP <input type="checkbox"/> DOL <input type="checkbox"/> DOH <input type="checkbox"/> DCA | Type Notification <input checked="" type="checkbox"/> Initial <input type="checkbox"/> Amended Amendment # _____ <input type="checkbox"/> Emergency (including justification) <input type="checkbox"/> Cancellation | Street Address Picatinny Arsenal | | | | | | | |
| | | City, State, Zip Code Picatinny, NJ 07806 | | | | | | | |
| | | Name of Contact Danny Castellano | Telephone Number 973-724-4472 | | | | | | |
| FACILITY INFORMATION | | | | | | | | | |
| Name of Facility Where Abatement is Taking Place (3) Building B-57 | | Type of Facility (4) <input type="checkbox"/> School (K-12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input checked="" type="checkbox"/> Other (i.e. private & commercial buildings, homes, etc.) | | | | | | | |
| Street Address Picatinny Arsenal | | Square Feet 4180 | # of Floors 1 | | | | | | |
| City (5) Picatinny | | Bldg. Age 50+ | | | | | | | |
| County (6) Morris | County Code (7) (STATE USE ONLY) _____ | Current Use (Prior if being demolished) Warehouse | | | | | | | |
| Name of Monitoring Firm Hired by Building Owner (8) N/A | | ASCM No. | Name of Abatement Contractor (9) Bako Construction & Restoration, Inc. | | | | | | |
| Street Address | | Street Address 265 A Route 46 Suite 3D | | | | | | | |
| City, State, Zip Code | | City, State, Zip Code Totowa, NJ 07512 | | | | | | | |
| Project Manager for Monitoring Firm | | Telephone No. 973-256-7010 | License No. 0666 | | | | | | |
| Start Date (10) 08/08/2016 | Scheduled Completion Date (11) 08/17/2016 | Name of OSHA Monitor Bako Construction & Restoration, Inc. | | | | | | | |
| Occupancy Status During Abatement (Check Only One) <input checked="" type="checkbox"/> Facility Closed/Vacated During Entire Period of Abatement <input type="checkbox"/> Abatement Performed Outside of Normal Facility Hours <input type="checkbox"/> Other - Describe: _____ | | Street Address 265 A Route 46 Suite 3D | | | | | | | |
| | | City, State, Zip Code Totowa, NJ 07512 | | | | | | | |
| Scope of Work (Check All That Apply) | | | | | | | | | |
| <input type="checkbox"/> ≥3 sf or ≥3 lf <input checked="" type="checkbox"/> ≥160 sf or ≥260 lf | | <input checked="" type="checkbox"/> Renovation <input type="checkbox"/> Demolition <input type="checkbox"/> Full Containment with Negative Pressure <input type="checkbox"/> Mini-Enclosure <input type="checkbox"/> Glovebag Procedure <input checked="" type="checkbox"/> Non-Exempted (*) and Non-Friable Procedure | | | | | | | |
| Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13) | Is Location Normally Used Solely by Maintenance/Custodial Staff? (12) | | | Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous) | Amount (Specify SF or LF) | Abatement Type | | | |
| | Yes | No | N/A | | | Removal | Repair | Encapsulate | Enclosure |
| Building B-57 | | X | | Asbestos Roof Panels | 4180 SF | X | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Name of Registered Waste Hauler Bako Construction & Restoration, Inc. | | NJDEP Waste Hauler ID No. 20889 | Cubic Yards of Waste 50 | Name of Registered Landfill Tullytown Resource Recovery Facility | | | | | |
| City, State Totowa, NJ | | Disposal Date 08/17/16 | | City, State Tullytown, NJ | | | | | |
| Completed by Damir Valjevac | | Title Project Manager | | Signature  | | | | Date 07/01/2016 | |